

Pin assignment

Pin assignment number: **2528**

Index:

25.07.2011

Connector name: **9-pol.CONTACT** Pin-count: **9**

+ 2529 + 2584 = K188

Page: 1/1

Pin	Designation	Description	Level	Driver	NC	Color
1	IBS_DO2_OUT	Data output Remote OUT	RS 422	RS 422		white
2	IBS_DO2_OUT	Data output Remote OUT	RS 422	RS 422		brown
3	IBS_DI2_IN	Data input Remote OUT	RS 422	RS 422		green
4	IBS_DI2_IN	Data input Remote OUT	RS 422	RS 422		yellow
5	IBS_Ground2	Ground galvanically isolated	0V			gray
6	not connected					
7	Supply Voltage IN	Supply voltage	11-27V			blue
8	Ground IN	Ground	0V			red
9	IBS_RBST_IN	Remote Bus Connector				black

REMOTE OUT : (9 pole Socket)

,

Pin assignment

Pin assignment number: 2529

Index:

25.07.2011

Connector name: 9-pol.CONTACT Pin-count: 9

+ 2528 + 2584 = K188

Page: 1/1

Pin	Designation	Description	Level	Driver	NC	Color
1	IBS_DO1_OUT	Data output Remote IN	RS 422	RS 422		white
2	IBS_DO1_OUT	Data output Remote IN	RS 422	RS 422		brown
3	IBS_DI1_IN	Data input Remote IN	RS 422	RS 422		green
4	IBS_DI1_IN	Data input Remote IN	RS 422	RS 422		yellow
5	IBS_Ground1	Ground galvanically isolated	0V			gray
6	not connected					
7	Supply Voltage IN	Supply voltage	11-27V			blue
8	Ground IN	Ground	0V			red
9	not connected					

REMOTE IN : (9 pole Plug)

,

Pin assignment

Pin assignment number: 2584

Index:

25.07.2011

+ 2528 + 2529 = K188

Connector name: with cable outlet Pin-count: 9

Page: 1/1

Pin	Designation	Description	Level	Driver	NC	Color
1	SSI_Clock-_IN	Clock input -	RS 422	RS 422		white
2	SSI_Clock+_IN	Clock input +	RS 422	RS 422		brown
3	SSI_DATA+_OUT	Data output +	RS 422	RS 422		green
4	SSI_DATA-_OUT	Data output -	RS 422	RS 422		yellow
5	Supply Voltage IN	Supply voltage	11-27V			blue
6	Ground IN	Ground	0V			red