

Pin assignment

Pin assignment number: 9927

Index:

30.08.2012

Connector name: 4-pol. M12-Bush

Pin-count: 4

+ 9928 + 9929 = K417

Page: 1/1

Pin	Designation	Description	Level	Driver	NC	Colour
1	TXD+	Data output +				yellow
2	RXD+	Data input +				white
3	TXD-	Data output -				orange
4	RXD-	Data input -				blue

Pin assignment

Pin assignment number: 9928

Index:

30.08.2012

Connector name: 4-pol. M12-Bush

Pin-count: 4

+ 9927 + 9929 = K417

Page: 1/1

Pin	Designation	Description	Level	Driver	NC	Colour
1	TXD+	Data output +				yellow
2	RXD+	Data input +				white
3	TXD-	Data output -				orange
4	RXD-	Data input -				blue

Pin assignment

Pin assignment number: 9929

Index:

30.08.2012

Connector name: 4-pol. M12-Connector

Pin-count: 4

+ 9927 + 9928 = K417

Page: 1/1

Pin	Designation	Description	Level	Driver	NC	Colour
1	Supply Voltage IN	Supply voltage	11-27V			brown
2	not connected					
3	Ground IN	Ground	0V			blue
4	not connected					

WARNING !!

'De-energize the system before carrying out wiring work or opening and closing electrical connections !!!
Short-circuits, voltage peaks, etc. can cause operating failures and uncontrolled operating states, as well as serious personal injuries and damage to property.

Verdrahtungsarbeiten, Öffnen und Schließen von elektrischen Verbindungen nur im spannungslosen Zustand durchführen !!! Kurzschlüsse, Spannungsspitzen etc. können zur Fehlfunktion und unkontrollierten Zuständen der Anlage bzw. zu erheblichen Personen- und Sachschäden führen.