

# Pin assignment

+ 2523 = K438

Pin assignment number: 3358

Index:

29.10.2014

Connector name: 12-pol CONTACT

Pin-count: 12

Page: 1/1

Pin	Designation	Description	Level	Driver	NC	Colour
1	not connected					
2	not connected					
3	DATA+_OUT	Data output +	RS 422	RS 422		green
4	DATA-_OUT	Data output -	RS 422	RS 422		yellow
5	not connected					
6	not connected					
7	not connected					
8	Direction IN	Change of counting direction	Supply Voltage		0	red
9	Preset1_IN	Preset value 1	Supply Voltage		0	black
10	not connected					
11	Supply Voltage IN	Supply voltage	11-27V			gray/pink
12	Ground IN	Ground	0V			red/blue

## WARNING

'De-energize the system before carrying out wiring work or opening and closing electrical connections !

Short-circuits, voltage peaks, etc. can cause operating failures and uncontrolled operating states, as well as serious personal injuries and damage to property.

Verdrahtungsarbeiten, Öffnen und Schließen von elektrischen Verbindungen nur im spannungslosen Zustand durchführen ! Kurzschlüsse, Spannungsspitzen etc. können zur Fehlfunktion und unkontrollierten Zuständen der Anlage bzw. zu erheblichen Personen- und Sachschäden führen.

# Pin assignment

+ 3358 = K438

Pin assignment number: 2523

Index:

29.10.2014

Connector name: 12-pol CONTACT

Pin-count: 12

Page: 1/1

+ 2523 = K438

Pin	Designation	Description	Level	Driver	NC	Colour
1	Heating_IN	Heating +24V				white 0,5
2	Heating_Ground_IN	Heating Ground				brown 0,5
3	not connected					
4	not connected					
5	Heating_Ground_IN	Heating Ground				brown 0,5
6	not connected					
7	not connected					
8	not connected					
9	Heating_IN	Heating +24V				white 0,5
10	not connected					
11	not connected					
12	not connected					

## Connector coding

' ! Connector Y - coded !

\*\*\*\*\*